





<i>IICc</i>	AUTOMATION INSPECTION ITEMS (FINISHED PRODUCTS)	Date : 2017/11/15
1. Mobile Phone		
1.	<a href="#">Scratch</a>	
2.	<a href="#">Black/White spot</a>	
3.	<a href="#">Gap defect</a>	
4.	<a href="#">Notch</a>	
5.	<a href="#">Speaker hole defect</a>	
6.	<a href="#">Logo print defect</a>	

*IICc*





1 Scratch		
2013-7-30	4.7" (mobile phone)	<a href="#">Go to TOP</a>
		

*IICc*

2 Black/White spot		
2013-7-30	4.7" (mobile phone)	<a href="#">Go to TOP</a>
		

*IICc*

3 Gap defect		
2013-7-30	4.7" (mobile phone)	<a href="#">Go to TOP</a>
		

*IICc*

4 Notch

2013-7-30

4.7" (mobile phone)

[Go to TOP](#)



*IICc*

5 Speaker hole defect

2013-7-30

4.7" (mobile phone)

[Go to TOP](#)



*IICc*

6 Logo print defect		
2013-7-30	4.7" (mobile phone)	<a href="#">Go to TOP</a>
		

*IICc*



